

## **VOLUNTARY SAFETY NOTIFICATION CAMPAIGN**

### **REPLACEMENT PART AVAILABLE FOR PRIMO VIAGGIO SIP 30/30**

Peg Perego has taken this voluntary action because mold flash may exist on the car seat restraint harness adjuster covers manufactured between July 2007 and March 2008. (Mold flash is a situation where excess plastic leaks from the mold and creates an unintended edge on the component.) Peg Perego has received 91 complaints of cuts, scratches or abrasions on the feet or legs of bare-footed infants. In the reported incidents, the children were not seriously injured.

Although this part passed the Sharp Edge Test as mandated under federal safety testing procedures, the mold has been redesigned to eliminate the problem on subsequent production.

A new adjuster cover has been sent to all customers whose registered Peg Perego Primo Viaggio SIP 30/30 car seats fall within the July '07-March '08 manufacturing window. To ensure no one is missed, Peg Perego will send a new adjuster cover free of charge to any customer who requests one by calling Peg Perego toll-free at 1-800-671-1701.

Child safety and comfort is Peg Perego's top priority. To ensure that it remains as such, Peg Perego is providing an Online Associate to facilitate customer interaction on the web. It is Peg Perego's goal to effectively and proactively communicate with the public through this medium.